

PRIORITY

SECRET

PRITY [REDACTED] 2654 SIX FIVE FOUR

25X1A

IN 12277

14 JAN 57 18 20z

25X1A

1. [REDACTED]

2. FIVE APPROX ONE ZERO ZERO FOOT TEST STRIPS PROCESSED AS FOLL WITH RESULTS INDICATED:

A. NORMAL PROCESSING ESTABLISHED BY NESVIG, INCLUDING DOUBLE STRENGTH NOVEMBER HOTEL DASH FIVE HARDNER. RESULTS: STICKINESS IN DRYER.

B. REPEAT OF TEST ALFA ABOVE, EXCEPT DEVELOPER AND SHORTSTOP OMITTED. RESULTS SAME AS ALFA, ABOVE.

C. NORMAL PROCESSING, OMITTING DEVELOPER USING TRIPLE STRENGTH HARDNER. RESULTS: SEVERE STICKINESS IN DRYER.

D. DEVELOPER AND SHORTSTOP OMITTED. USING QTE POWDERS, FIXING BATH HARDNER UNQTE ADDED TO LIQUID HYPO. RESULTS SAME AS ALFA AND BRAVO, ABOVE.

E. AEROSOL, DEVELOPER AND SHORTSTOP OMITTED. NOVEMBER HOTEL DASH FIVE USED ACCORDING TO MANUFACTURERS INSTRUCTIONS. RESULTS SAME AS ALFA, BRAVO AND DELTA, ABOVE.

3. PPEARS THAT HARDNER NOT BASIS OF PROBLEM STICKINESS IN DRYER. TEST LEADER RUN THROUGH DRYER WET INDICATES NO PROBLEM WITHIN DRYER. TESTING WILL BE CONTINUED. REQUEST

25X1A

[REDACTED] COMMENTS ADVICE SOONEST.

25X1A

CFN: [REDACTED] HARDNER HYPO AEROSOL NOT 25X1A

NO

SECRET

6441000